



- Notes:**
1. This drawing is the property of ACP (Concrete) Ltd and is not to be copied in any way without prior written approval from AXP (Concrete) Ltd.
 2. Brackets A to be clipped to steel work using M12 bolts into cast in sockets. 4 No Brackets per panel (1 in each corner).
 3. Fixing Angles have two fixing scenarios:
 - a. Fix to prestressed concrete panels using M12 excalibar bolts or equivalent to the manufacturers specification.
 - b. Fix to steel column/beams using M12 bolts c/w nut & washer.

It is the responsibility of the main contractor to notify ACP(Concrete)Ltd of any subsequent revisions which may affect this design.

Rev.	Dwn	Date

Checked By _____

ACP (Concrete) Ltd
 Office 8, Uttoxeter Business Park
 Centre, Tow Meadows Ways,
 Uttoxeter, Staffordshire, ST14 8AZ
 Tel:01889 598660 Fax:01889 568160

Job Title:
 TYPICAL FIXING ARRANGEMENT
 TO FACE OF COLUMNS & INSIDE
 COLUMN WEBB

Drawn: TAW	Scale: NTS	Date: 20/05/08
Drawing No.	2001	-